

# AR51X VACUUM WAND PARTS


Part #	Description	QTY
AR51X	Handle Gekko Wand Complete- Vacuum Only	1
NA030	Gekko Wand Tube with bracket	1
NA030A	Vent Slide	1
NM5855	Gekko Tool Coupler Assembly	1
NM4080	10-32 x 1 5/8" Screw	3
NM4028	10-32 Hex Nut Zinc Plated	3
NA031B	Spray Gun Body – No valve	1
NM5629	Screw 4mm x 20 PPH Self tap Black	4
NM5858	Gekko Grip Handle Assembly (Includes mounting screws & nuts)	1



# AR51X VACUUM WAND PARTS

Spray Gun Body NA031B – Without screws - Modified for mounting.

- Install four screws NM5629 into the holes near the back of the plastic body.
- Drill three 3/16" holes all the way through plastic body in the three holes near the front of the plastic body.




# AR51X VACUUM WAND PARTS

## Gekko Tool Coupler Assembly NM5855

Includes both sides of coupler and two 8-32 x 7/16" Phillips Pan Head Screws

APPLY GREASE HERE



Left Coupler




Right Coupler



8-32 x 7/16" Phillips Pan Head Screws



Gekko Tool Coupler Assembly  
Installed on Wand Tube



NM5858 Gekko Grip Handle Assembly

NM5698 – Screw 10-32 x 1/2" PPH SS  
NM4028 – Nut 10-32 Nylock